

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1779	DATE	September 13, 2011
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Japan K.K.)		
DESCRIPTION OF DEFECT	Engine stall may happen when throttle is deceleration since engine management calibration has small technical problem. Then finally bike may lose control if engine stall happen in unexpected situation when bike is deceleration		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CA	Tiger 800	2010 - 2011	52
CB	Tiger 800 ABS	2011	30
CC	Tiger 800 XC	2010 - 2011	36
CD	Tiger 800 XC ABS	2011	20
		TOTAL	138