

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN NO.	2826	DATE	16th. Sept. 2011
MANUFACTURER	TCM CORPORATION		
DESCRIPTION OF DEFECT	<p>There is something of the common rail which is a part of fuel system is insufficiency. Therefore, If the machine is used continuously, there is possibility that the common rail will crack, and then worst, fuel will leak.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
JDS-F144	FD135-4 FD150S-4 FD160S-4	2008 ~ 2009	13	
JDS-F146	FD150-3 FD200-3 FD230-3	2008 ~ 2010	12	
TOTAL			25	