

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2822	DATE	Sep. 22 2011
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On heavy-duty tractors, the strength of the mounting fixture for the muffler cover (heat insulating plate) is insufficient. If the vehicle continues to be used in this condition, the fixture may break due to the vibration during driving and the muffler cover may fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-FP54VDR	FUSO	2009	1
LDG-FV50VJR		2010~2011	62
LKG-FP54VDR		2010~2011	483
LKG-FP54VER		2010~2011	99
LKG-FP54VGR		2010~2011	40
		TOTAL	685