

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2828	DATE	September 27 ,2011
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		When the air tank for brakes, etc, is remounted on a heavy-duty truck, the air tank bracket may be cracked by body vibrations during running since the bracket strength is not sufficient. If the bracket is not reinforced, the bracket may be broken while the truck is in service and in an extreme case, the air tank may fall onto the ground when the truck is running.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-CYZ77AJ	GIGA	2010	1
LKG-CXE77A		2010	2
LKG-CVR77A		2010-2011	5
LKG-CXY77AJ		2010-2011	7
		TOTAL	15