

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2829	DATE	Sep.27.2011
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty sight seeing buses equipped with a swing type door, due to inadequate structure to fix the swing arm to the door with a bracket, the nut to tighten the joint bolt to the bracket can be loose and the joint bolt broken. These causes the swing door fails to be closed securely, and drop off if the worst comes.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-RU1ESAA	HINO SELEGA	2005~2010	2,586
PKG-RU1ESAA			
PKG-RU1ESAAKAI			
LKG-RU1ESBA		2010~2011	252
BJG-RU1ASAR		2008~2010	35
ADG-RU8JHAA		2006~2010	411
BDG-RU8JHAA			
BDG-RU8JHAAKAI			
LDG-RU8JHBA		2010~2011	35
SDG-RU8JHBA			
		TOTAL	3,319