

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2830	DATE	September 27 ,2011
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain heavy duty sight seeing buses equipped with a swing type door, due to inadequate structure to fix the swing arm to the door with a bracket, the nut to tighten the joint bolt to the bracket can be loose and the joint bolt broken. These causes the swing door fails to be closed securely, and drop off if the worst comes.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-RU1ESAJ PKG-RU1ESAJ	ISUZU GALA	2005-2010	1,430
LKG-RU1ESBJ		2010-2011	158
ADG-RU8JHAJ BDG-RU8JHAJ		2006-2010	155
LDG-RU8JHBJ SDG-RU8JHBJ		2010-2011	33
		TOTAL	1,776