

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2832	DATE	Sep.29 2011
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some light-duty trucks, data for meter cluster ECU may not be inputted properly by the automatic updating program when replacing the meter cluster. This may cause faulty speedometer indication, etc.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FBA00	FUSO CANTER	2010~2011	2
SKG-FBA20		2010~2011	15
SKG-FEA20		2011	1
SKG-FEA50		2011	1
SKG-FEB20		2011	1
SKG-FEB50		2010~2011	11
SKG-FEB70		2011~2011	3
SKG-FEB90		2010	1
		TOTAL	35