

CHILD RESTRAINT SYSTEM SAFETY RECALL CAMPAING IN JAPAN

Domestic Import Items

CAMPAING No.	装5	DATE	4-Oct- 2011
MANUFACTURER	CARMATE MFG. CO., LTD.		
DESCRIPTION OF DEFECT	For inappropriate way of adjust lever to be fixed with Child Restraint Seat, tapping screw may be getting loose by using harness adjuster repeatedly forgetting infant on and off. This may possibly come off the tapping screw at the worst which may cause the seat un-usable as harness adjuster becomes unadjustable.		

COMMERCIAL NAME	TYPE	CLASSIFICATION	MODEL YEAR RECALLED	NUMBER OF ITEMS
Ailebebe Kurutto NT	E4 04443842	Groups O + / I	A serial number L10B800001 ~ L10B802582 (2010. 1. 28. ~ 2010. 3. 9.)	45, 624pcs.
ALB820				
ALB821				
ALB822				
ALB830			L00B802585 ~	
ALB831			L00B839868	
ALB832			(2010. 3. 18. ~	
ALB840			2010. 12. 28.)	
ALB850				
ALB851			L10B839869 ~ L10B855233 (2011. 1. 5. ~ 2011. 7. 14.)	
			TOTAL	