

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-1785	DATE	Oct 6, 2011
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japoan Ltd. )		
DESCRIPTION OF DEFECT	Vehicles may have a fuel tank leak at the quick connectors that are used to link the left and right fuel tanks. The customer may notice a fuel odor while the vehicle is being refueled, driven, or after it is parked. If the leak becomes large enough, a small amount of fuel may be observed dripping on the ground. The leak may also result in a diagnostic code being set and the illumination of the Check Engine light on the instrument cluster.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-X215	XLR	2004	15
GH-CY25E	CORVETTE	2004	5
		TOTAL	20