

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CANPAIGN No.	2834	DATE	OCT. 14. 2011
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	On the garbage-truck which we installed a plunger-type hydraulic pump, the pump-bracket may crack because of its strength shortage. When users continue using it, as the worst result, a hydraulic pump may drop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-NMR85N	ELF	2007~2009	8
BKG-NKR85AN		2008~2011	23
BKG-NMR85AN		2007~2011	110
BKG-NMR85N		2010~2011	3
NFG-NKR82XAN		2008~2009	3
NFG-NMR82AN		2008~2009	28
NFG-NMR82N		2007~2010	10
NFG-NPR82XN		2009~2010	3
NKG-NMR82AN		2007	1
PDG-NKR85YN		2009	1
PDG-NPR75N		2008~2009	11
PKG-NPR75N		2008	7
SFG-NKR82XAN		2010	2
SFG-NMR82AN		2010~2011	15
PDG-FRR34S2	FORWARD	2008	1
PDG-FTR34S2		2009	3
PKG-FRR90S1		2008	1
PKG-FRR90S2		2008~2009	4
PKG-FSR90S2		2008~2009	2
NBG-BZU300	DYNA/TOYOACE	2010	1
BDG-MK36C	CONDOR	2008	1
NFG-BKR82XAN		2008	1
NFG-BMR82AN		2009	1
NFG-BPR82XN		2008	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-GC7JEWAkai	RANGER	2008~2009	2
BDG-FC7JGWA		2008	1
BDG-GD7JGWA		2009	2
BKG-FC7JGYA		2008	1
BDG-XZU304E	DUTRO	2009	1
BDG-XZU304X		2007~2011	42
BDG-XZU334M		2008	1
BDG-XZU404M		2008	1
BDG-XZU404Xkai		2009~2010	22
BDG-XZU414M		2008~2010	2
BJG-XKU304X		2008~2010	29
BJG-XKU304Xkai		2009	18
BKG-XZU304E		2010~2011	4
BKG-XZU304X		2010~2011	8
NBG-BZU300X		2008~2011	6
NBG-BZU340		2010	1
PDG-FE73D	CANTER	2007~2010	42
PDG-FE83DY		2008~2010	10
PDG-FK71F	FIGHTER	2008	2
PDG-FK71R		2009	1
		TOTAL	437