

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1786	DATE	2011/10/18
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	It is possible that the electrical contact failure happens in the brake lamp switch due to the wear resulting from durability insufficiency or deformation resulting from increase in temperature. Therefore, if the vehicle is used under this condition, this switch may not work properly and consequently brake lamp may not be lit. In the worst case, cruise control may not be released by foot brake operation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-163154	ML320	1999 ~ 2002	1,768
GF-163154	ML320	2000	205
GH-163154	ML320	2001 ~ 2002	49
KH-163113	ML270CDI	1999 ~ 2002	1,266
GF-ML55	ML55	2000 ~ 2002	146
GH-163174	ML55	2002 ~ 2003	61
GF-163172	ML430	1999 ~ 2001	77
		TOTAL	3,572