

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1787	DATE	October 19 th , 2011
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate value setting of optical fiber sensor for pedestrian head safety system, the active engine hood of the pedestrian head safety system may possibly not activate when the front part of vehicle in question comes into collision with a pedestrian.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LW30	BMW 640i Cabriolet	2010 ~ 2011	104
ABA-LZ44	BMW 650i Cabriolet	2010 ~ 2011	44
		TOTAL	148