

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-1791	DATE	Oct 21, 2011
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japoan Ltd.)		
DESCRIPTION OF DEFECT	The diagnostic function of the directional indicators is inoperative, causing false trouble codes to be stored in the Body Control Module.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-T345E ABA-T345F	H3	2007 - 2008	703
		TOTAL	703