

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1789	DATE	October.27. 2011
MANUFACTURER	Wuyang-Honda Motors (Guangzhou) Co., Ltd.		
DESCRIPTION OF DEFECT	<p>A machine to apply grease to the pivot of the front brake lever of the brake system was not properly controlled at the start of the working shift. Due to this, grease was not sufficiently applied to the pivot to cause corrosion of pivot bolt during usage, and prevent the brake to move smoothly. If the vehicle is continuously driven in such condition, the brake may drag even when the lever is released. In the worst case, the front wheel will stop rotating at a low vehicle speed and the vehicle may fall.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBJ-JF19	LEAD	2010~2011	18,344
		2010	48
		TOTAL	18,392