

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai 1792	DATE	October 31, 2010
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	It is possible that rear drive shafts that do not meet the required specification due to a manufacturing defect were installed in the affected vehicles. As a result, it may not be possible to ensure the durability of the drive shafts over the service life of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-997MA170	911 Turbo	2010	3
TOTAL			3