

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2844	DATE	Nov.4 2011
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some light-duty trucks, the strength of the knuckle adapter mounting bolts may be insufficient to withstand the excessive stresses caused by the improperly machined knuckle fitting bore in the adapter. If the vehicle continues to be used in this condition, mounting bolts will fall off or break. In the worst case, the knuckle adapter will swing out of position and damage the front brake hose, leading to an inoperable front brake.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FEB90	FUSO CANTER	2011~2011	2
		TOTAL	2