

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2842	DATE	8th.Nov. 2011
MANUFACTURER	TCM CORPORATION		
DESCRIPTION OF DEFECT	<p>In the forklift, the direction of port of the exhaust pipe for options serves as facing the right. Therefore, there is a possibility that the gas which emits may have a bad influence on other traffic.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
F 24	FD30Z5 FD30T6	1996 ~ 2003	6	
F 30	FG20N5	1996	1	
F 31	FD25Z5 FD25T6	1996 ~ 2003	2	
F 67	FHD20Z5 FHD25Z5	1997 ~ 2001	5	
F 68	FHG30N5 FG30T6H	1996 ~ 2002	5	
F 69	FHD30Z5	1996 ~ 2000	10	
F 70	FG25N16 FG25T17	1999 ~ 2002	2	
F 71	FD20Z16	1998	1	
F 75	FD10Z18	1996	1	
F 96	FD25C6H	2003	1	
F 97	FD30C6H FD30T6H	2003	3	
F 110	FD30T7	2003	1	
SA - F111	FD25T18	2004	1	
KDN - F120	FD25C3	2010	4	
F 128	FHG30T3	2005 ~ 2006	4	
KDN - F141	FHD30T3A	2009	1	
KDP - F142	FD40T2	2011	1	
EBT - F153	FHGE30T4	2008	1	
TOTAL			50	