

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2845	DATE	November 8, 2011
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Contact with the steered rear tires or side of rims and the rear axle frame on forklift trucks might happen when the wheels are steered at the maximum steering angle because their clearance is not enough. Therefore, such condition being continued, the rear tires or the rims might be damaged in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-M248	FD80	2008~2011	10
TOTAL			10