

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2853	DATE	November 15,2011
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the welfare vehicles which have the caring rotating seat in the passenger seating position, due to an inappropriate manufacturing procedure at the company who customized the vehicles, the different type of seatbelt buckle may have been installed in the subject seat. As a result, the subject buckle could not hold the seatbelt completely and, in the worst case scenario, the seatbelt could be unlatched.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-HA1W	i	2011	1
DBA-HA1W		2011	2
		TOTAL	3