

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1794	DATE	Nov 16, 2011
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	On vehicles with curtain airbag, harness for rear side crash sensor might not be installed properly. As a result, airbag activation would be delayed in case when curtain airbag activates.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-9NBJX	VW Polo 1.8T GTI	2006-2007	2,095
GH-9NBKY	VW Polo 1.4	2005-2007	27,469
GH-9NBTS	Polo 1.6	2007	5,783
ABA-9NBJX	VW Polo 1.8T GTI	2008-2009	313
ABA-9NBKY	VW Polo 1.4/55kw	2007	128
ABA-9NBTS	Polo 1.6	2007-2009	4,412
ABA-9NBUD	VW Polo 1.4 59kw	2008-2009	10,536
		TOTAL	50,736