

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No .	2 8 5 8	DATE	November 21 , 2011
MANUFACTURER	NIPPON YUSOKI C O .,LTD.		
DESCRIPTION OF DEFECT	In fixed platform truck, due to defective processing at the part (Motor-support) for attaching the traction motor to the power transmission device, there are some which were attached after the core of the output shaft of the traction motor and the input shaft of the power transmission device had shifted. It would become possible for the spline of the input shaft and coupling of the power transmission device, and the output shaft of the traction motor to be worn down, and malfunction certain traveling operation.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
NICHIYU 471AB	E L E T R U C K	2008 ~ 2011	2 8
TOTAL			2 8