## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No .	2859	DATE	November 21, 2011		
MANUFACTURER	NIPPON YUSOKI C 0 .,LTD.				
DESCRIPTION OF	In electric fork lift trucks, due to defective processing at the part				
DEFECT	(End-cover) of the traction motor, there are some which were attached to				
	the reduction gears after the output shaft of the traction motor had				
	inclined. It would become possible for the output shaft to break, and				
	malfunction certain tra	aveling operation.			

TYPE	COMMERCIAL NAME	MOI YE RECA	AR	NUMBER OF VEHICLES
NICHIYU ZAF -221E	TRANSER	2 0 1 1		1 2
			TOTAL	1 2