

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2854	DATE	Nov.24.2011
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty city buses, due to inadequate program of engine control, when engine load increases at idling engine speed, combustion gets poor and an exhaust gas reduction cooler is blocked up by deposition of carbon. If the vehicle is operated under the conditions continuously, the blades of turbocharger can be defective, resulting in lighting of the engine check lamp and lack of power for the smooth running of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LJG-HU8JLGP	HINO	2010~2011	51
LJG-HU8JMGP	Blue Ribbon City	2010~2011	27
		TOTAL	78