

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1798	DATE	November 28, 2011
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	On the brake system, rear brake hoses on the calipers could be coming into contact with neighboring components. Over time, friction could damage the brake hose, causing the "brake fluid level" warning light to come on or might be lead brake system failure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-A75F01 ABA-A7C5F01	Peugeot 207 Peugeot 207CC	2010-2011	34
		TOTAL	34