

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-1799	Date	December, 2, 2011
Manufacturer	Jaguar Cars Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	The FLBJ (Front Lower Ball Joint) may fail as a result of an under torque condition due to external shock inputs, which reduces clamp load in the joint formed between the FLBJ and the suspension lower control arm. This may result in bending fatigue of the joint, which in some cases could result in fracture in of the FLBJ stud at the first thread, leading to separation of the lower control arm from the suspension knuckle. The affected front road wheel becomes disconnected from the lower control arm.		

Type	Commercial name	Model year recalled	Number of vehicles
GF-J01FA	S-TYPE 3.0 V6 S-TYPE 3.0 V6 SE	1999-2002	1,921
GF-J01FB		1999 - 2002	1,005
GF-J01GA	S-TYPE 4.0 V8	1999 - 2002	716
GF-J01GB		1999 - 2002	60
Total			3702

(JIS A4 size)