

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI – 1802	DATE	December 2nd, 2011
MANUFACTURE	Rolls-Royce Motor Cars Limited The Drive, Westhampnett, Chichester, West Sussex, PO18 0SH, UK (Contact in Japan : Japan Representative Office - R-R Motor Cars Ltd)		
DESCRIPTION OF DEFECT	At the electric auxiliary coolant pump for the turbocharger, design appraisal of the circuit for activating the pump may have been insufficient. Therefore, when driving the vehicle under status quo, metallic substance may form on the circuit board and short circuit may occur, which could lead to smoldering of the plug connection and, in worst case, it can cause vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-664S	Rolls-Royce Ghost	2010	56
		TOTAL	56