

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-1803	DATE	December 2nd, 2011
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH+Co.KG (Japanese Importer: Nicole Racing Japan Co.,Ltd)		
DESCRIPTION OF DEFECT	At the electric auxiliary coolant pump for the turbocharger, design appraisal of the circuit for activating the pump may have been insufficient. Therefore, when driving the vehicle under status quo, metallic substance may form on the circuit board and short circuit may occur, which could lead to smoldering of the plug connection and, in worst case, it can cause vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-JM10	B7 Biturbo	2009 ~ 2010	11
ABA-KM10	B7 Biturbo Long	2009 ~ 2010	10
ABA-AM10	B5 Biturbo	2010	3
		TOTAL	24