

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2 8 6 7	DATE	December.8.2011
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	With regard to the differential carrier on rear / front axle of heavy-duty truck with low platform, due to the inappropriate play on the spline at front side of the differential carrier, there may be excessive force toward the flange bolts which fixed the flange and spline shaft to be loaded. The continuous use in this condition may result in a damage of the bolt, and in the worst case, the flange will come off with propeller shaft allowing the vehicle down on the road.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-CG48XWX	—	1999 – 2003	193
KL-CG48YWV KL-CG48YWW KL-CG48YWX	—	1999 – 2003	220
KL-CG48ZVX	—	1999 – 2003	37
KL-CG48ZWV KL-CG48ZWW KL-CG48ZWX	—	1999 – 2003	2,814
KL-CW48YVX	—	1999 – 2003	123
KL-CG48A	—	2003 – 2005	93
KL-CG48E	—	2003 – 2005	30
KL-CG48G	—	2003 – 2005	172
KL-CG48J	—	2003 – 2005	190
KL-CG48L	—	2003 – 2007	2,376
KL-CG48M	—	2003	2
KL-CG48N	—	2003 – 2004	5
KL-CG48R	—	2003 – 2005	267
KL-CX48E	—	2003 – 2005	52
KL-CX48G	—	2003 – 2005	126
ADG-CG4XL PKG-CG4XL	—	2005 – 2008	17

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-CG4XA	—	2005 – 2010	49
ADG-CG4YA PKG-CG4YA	—	2005 – 2010	213
ADG-CG4YE PKG-CG4YE	—	2005 – 2010	27
ADG-CG4YL PKG-CG4YL	—	2005 – 2010	38
ADG-CG4ZA PKG-CG4ZA	—	2004 – 2010	5,291
ADG-CG4ZE PKG-CG4ZE	—	2005 – 2010	789
ADG-CG4ZL PKG-CG4ZL	—	2005 – 2010	408
ADG-CX4YA PKG-CX4YA	—	2005 – 2010	302
ADG-CX4YL	—	2005 – 2010	186
		TOTAL	14,020