

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	GAI-1808	DATE	Dec.26, 2011
MANUFACTURE	Caterpillar UK LTD (Caterpillar Japan LTD)		
DESCRIPTION OF DEFECT	<p>Raw tube was sourced from an alternative mill in China for a period of time. Mill's pickling process was not in control and tube was over-pickled resulting in grain boundary attack of the internal bore of the tube. There is a possibility that debris from the surface of tube of low-pressure fuel line can damage the injector valve seat resulting in high injector leak off and in some instances failure to decrease the engine power and start.</p> <p>Therefore it is necessary to replace the tube of low-pressure fuel line with good quality ones which was supplied from original mill in Austria .</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-PED	924HZ	2010	6
EDR-FTD	930H	2010	4
		TOTAL	10

Note: