

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import~~ Vehicles

CAMPAIGN No.	Gai-1810	DATE	2012/1/12
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	Due to improper material composition and improper injection molding, the seal ring of fuel filter may not have enough performance to keep the fuel pressure. Therefore, if the vehicle is used under this condition, this seal ring may not keep fuel pressure properly and consequently fuel may leak from the filter.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-212024C	E350BlueTEC	2010 ~ 2011	432
LDA-212224C	E350BlueTEC STATIONWAGON	2010 ~ 2011	518
FDA-164125	ML350 BlueTEC 4MATIC	2010 ~ 2011	90
		TOTAL	1,040