

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2881	DATE	JANUARY 26,2012
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	THE RETAINING FORCE OF THE CRANKSHAFT OIL SEAL FITTED IN THE ENGINE FRONT CASE MAY HAVE BEEN DECREASED DUE TO THE COMBINED FACTOR SUCH AS THE MACHINING VARIABILITY OF THE FRONT CASE AND THE PRESS FITTING VARIABILITY OF THE OIL SEAL. BECAUSE OF THIS, THE SUBJECT OIL SEAL WOULD COME OUT AND THE ENGINE OIL WOULD BE LEAKED GRADUALLY CAUSING THE OIL PRESSURE WARNING LIGHT TO BE ILLUMINATED, AND IF USE CONTINUES UNDER THIS CONDITION, THE INNER PARTS OF THE ENGINE COULD BE SEIZED RESULTING IN THE VEHICLE UNABLE TO BE DRIVEN.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-H42A	MINICA	2004 TO 2006	3,197
CBA-H47A		2004 TO 2006	764
GBD-H42V		2004 TO 2006	12,095
GBD-H47V		2004 TO 2006	1,728
LA-H81W	eK-WAGON eK-SPORT eK-CLASSY eK-ACTIVE	2004	33
UA-H81W		2004	334
CBA-H81W		2004 TO 2006	22,005
DBA-H81W		2004 TO 2006	42,227
GD-U61T GD-U61TP	MINICAB	2001 TO 2003	13,843
GD-U62T GD-U62TP		2001 TO 2002	17,616
LE-U61T LE-U61TP		2002 TO 2004	14,309
LE-U62T LE-U62TP		2002 TO 2004	18,818
GBD-U61T GBD-U61TP		2004 TO 2006	7,083
GBD-U62T GBD-U62TP		2004 TO 2006	11,135
GD-U61V		2001 TO 2003	17,511
GD-U62V		2001 TO 2003	7,269
LE-U61V		2002 TO 2004	23,948
LE-U62V		2002 TO 2004	8,380
GBD-U61V		2004 TO 2006	10,520
GBD-U62V		2004 TO 2006	5,165

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-U61W	TOWNBOX	2001 TO 2002	2,377
GF-U62W		2001 TO 2002	1,745
TA-U61W		2002 TO 2004	3,661
TA-U62W		2002 TO 2004	2,903
ABA-U61W		2004 TO 2006	528
ABA-U62W		2004 TO 2006	1,336
CBA-U61W		2004 TO 2006	1,327
CBA-U62W		2004 TO 2006	276
CBA-H91W	OTTI	2005 TO 2006	7,467
DBA-H91W		2005 TO 2006	21,530
LE-U71T	CLIPPER	2003	508
LE-U72T		2003	1,015
GBD-U71T GBD-U71TP		2005 TO 2006	3,230
GBD-U72T GBD-U72TP		2005 TO 2006	3,129
LE-U71V		2003	886
LE-U72V		2003	381
GBD-U71V		2005 TO 2006	6,442
GBD-U72V		2005 TO 2006	2,599
			TOTAL