

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2890	DATE	January 27, 2012
MANUFACTURER	Topre Corporation		
DESCRIPTION OF DEFECT	Due to the inadequate color selection of the door-ajar indicator lamp lenses installed on both side and rear of the refrigeration vehicle, the red indicator lamps are turned on when doors are full-latched, which color violates "Road Transport Vehicle Act Safety Standards Article 42."		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KR-NKR81LV	ELF	2002	1
KR-NPR81LV		2003	3
KR-NPR72LAV		2004	6
PA-NPR81N		2004-2007	19
PB-NKR81AN		2004	2
BKG-NPR85AN		2007	1
PJ-CYJ51W5A		GIGA	2004
KK-XZU410	DYNA	2002	1
KK-MK12A	CONDOR	2003	3
KK-FE70EB	CANTER	2003	1
KK-FE82EEV		2002-2003	8
KK-XZU302M	DUTRO	2002	2
KK-XZU341M		2002-2003	7
KK-XZU410M		2003	5
PB-XZU414M		2004	5
BDG-XZU414M		2007-2008	10
PK-FW1EXWJ		PROFIA	2004
BKG-FW1EXYJ	2007		1
		TOTAL	78