

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import Vehicle~~

CAMPAIGN No.	2887	DATE	Jan.31,2012
MANUFACTURER	Kobelco Cranes Co., Ltd.		
DESCRIPTION OF DEFECT	Certain units of the Crane had been applied with excessive amount of grease during the assembly of Bearings in the Axle Hub of the Travel Mechanism. This might lead to cases where the Oil Seal might be displaced losing its Sealing Function, and the leaked grease might attach to the Brake Shoe to make longer the Braking Distance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-EE02	RK250-7	2010 – 2011	4 0
TOTAL			4 0