

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-1815	DATE	February 20, 2012
MANUFACTURE	RENAULT SAS (Japanese Importer : Nissan Trading Co.,Ltd.)		
DESCRIPTION OF DEFECT	Material at a fitting point between an air mixture flap and its operating motor is air-conditioner mechanical unit was weak.  Therefore, the fitting point will be broken during using, then the motor can not operate the mixture flap, then air conditioner unit lose outlet of heated air.  That means defroster function for front screen does not work. It is possible to be out of the safety standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-KWK4M	Kangoo	2009 – 2010	487
ABA-KWK4MG	Kangoo	2010	33
		TOTAL	520