

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2895	DATE	Feb. 21, 2012
MANUFACTURER	ShinMaywa Industries, Ltd.		
DESCRIPTION OF DEFECT	Geometrical visibility of tail lamps and stop lamps is unsatisfactory in particular units of light duty dump trucks, due to mistake in fitting positions of tailgate stoppers, which are provided in order to prevent tailgate from interfering with chassis frame and surrounding equipments when opened downward.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG - NJR85AD	ELF	2011	14
SKG - NKR85AD			9
SKG - AJR85AD	ATLAS		3
SKG - AKR85AD			1
SKG - XZC630T	DUTRO		1
SKG - XZU630T			4
SKG - LJR85AD	TITAN		4
SKG - LKR85AD			5
		TOTAL	41