

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	2 9 1 6	DATE	Mar. 28, 2012
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	In the axle of the trailer, there is something wrong for the position of the axle mounting bracket, the direction of the axle and braking device is attached to the reverse sides. Therefore, the direction to the brake shoe of the braking device where the brake drum is rotated is reversed to a regular rotation, and the braking ability when going straight might not meet the safety standard of the road transportation vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DFPTF341AN (Modified)	Semi Trailer	2010-2011	6
DFPFH341AN (Modified)	Semi Trailer	2010	1
DFPTF241BN (Modified)	Semi Trailer	2010	5
Total			12

[Note] In the range of the chassis number of vehicle recall, may have vehicles that do not qualify are also included.