

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1826	DATE	April 02, 2012
MANUFACTURE	Automobiles CITROËN (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	On the connection between the clutch pedal and transmitter, may be incorrect clipping. The head of the master cylinder rod may occur come off from the clutch pedal and impossible to engage gears. The operation consists of checking the clipping of the clutch transmitter rod on the pedal.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-A5C5F04	Citroën DS3	2011	58
		TOTAL	58