

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1827	DATE	April 02, 2012
MANUFACTURE	Automobiles CITROËN (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	On the harness sleeve located at the connection of the tailgate and the body, it is not secured in a manner that can be guaranteed over time. After a number of tailgate movements, damage may occur to electrical wires which could lead to functional problems with hi mounted stop lamp, rear wiper and tail gate locking linked to the tailgate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-B5RFK GH-B5NFU GH-B5RFK	Citroën C4	2004-2006	281
		TOTAL	281