

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	2 9 1 8	DATE	Apr. 5 .2012
MANUFACTURER	Nichijo Manufacturing Co., Ltd.		
DESCRIPTION OF DEFECT	In the return spring parts of the pedal for the Rotary Snow Remover running speed control, some of this return spring parts contact with a guide pin when the pedal is pushed. Therefore, in continuous operation there is a possibility to break this return spring. In this case the pedal doesn't return from the maximum pushed position and the engine speed doesn't slow down.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
R 0 8 C	H T R 1 4 5	2 0 0 9	1
EDR-R 0 8 C	H T R 1 4 5	2 0 0 8 ~ 2 0 1 1	3 1
R 0 9 C	K B R 1 0 3	2 0 0 9	1
EDR-R 0 9 C	K B R 1 0 3	2 0 0 8 ~ 2 0 1 1	5 9
R 1 0 C	H T R 8 5	2 0 1 0	1
K D P - R 1 0 C	H T R 8 5	2 0 0 9 ~ 2 0 1 1	3 3
TOTAL			1 2 6