

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) / Import Vehicles

CAMPAIGN No.	2923	DATE	13, April, 2012
MANUFACTURER	Kobelco Construction Machinery Co., Ltd.		
DESCRIPTION OF DEFECT	Some hydraulic hoses in shovel loaders lack their strength because of improper material used in their fittings, which connect the hoses. Because of this, if these parts keep on being used in that condition, it will cause a crack and hydraulic oil leakage from it. In the worst case scenario, a hydraulic pump will draw the air and cause a damage that will lead to impossibility of traveling.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-YE04	SK125W	2011 ~ 2012	7
TOTAL			7