

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1836	DATE	April 25, 2012
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	On the fuse box under the bonnet, over tightening of the fixation nut for the electrical supply may occur the diagnostic warning light coming on and engine starting problem.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-B75F01S ABA-B7C5F02S	CITROEN C4 CITROEN DS4	2011	2
		TOTAL	2