

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	Gai-1843	DATE	May 2. 2012
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The issue involves connecting rod bolts that can come loose. At high engine operating temperatures the bolts can become completely loose and separate from the connecting rod. When the vehicle is used under this condition, the engine will be damaged and will lead the vehicle to stop running.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
S1000RR	BMW S1000RR	2011 - 2012	141
		TOTAL	141