

## VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

### Domestic Vehicles

<b>CAMPAIGN No.</b>	2931	<b>DATE</b>	May 7, 2012
<b>MANUFACTURER</b>	SUZUKI MOTOR CORPORATION		
<b>DESCRIPTION OF DEFECT</b>	Sealing performance between fuel hose and fuel filler pipe may become not enough, in case the fuel hose was incorrectly installed on the fuel filler pipe. If fuel is filled additionally into the fuel tank after auto-stop function on fuel filler nozzle worked at petrol station, fuel may be come out from the hose.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZC72S	SWIFT	2010 ~ 2012	48,238
DBA-ZD72S		2010 ~ 2012	6,908
		<b>TOTAL</b>	<b>55,146</b>