## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2933	DATE	May 14, 2012	
MANUFACTURE	TADANO LTD.			
DESCRIPTION OF DEFECT	The installation positioning of rear reflectors on subject aerial work platforms and road rail vehicles does not conform to geometric visibility requirements of safety standards.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-XZU404X	HINO, DUTRO	2009	1
BDG-XZU404X	HINO, DUTRO	2008 – 2012	27
		TOTAL	28