## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic / Import Vehicles

CAMPAIGN NO.	2932	DATE OF NOTIFICATION	15th.MAY.2012
MANUFACTURER	TCM CORPORATION		
DESCRIPTION OF DEFECT	The wiring may touch directly the edge of an electric box, because of insufficient rubber cover to the edge.  If continues using it, the wiring may be short - circuit and cause a small fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR - F136	ТСМ	2008 ~ 2012	60
EDR - F137	TCM	2008 ~ 2012	28
EDR - F138	TCM	2008 ~ 2011	6
		TOTAL	94