

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2940	DATE	May. 29. 2012
MANUFACTURER	TRANTECHS. CO. , LTD		
DESCRIPTION OF DEFECT	We have found the specific rivets we use to connect the upper fender boards with the Van body of the track inappropriate. So these rivets may be eroded, and the upper fender boards could fall off in the course of long-term using.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
LDG-FQ1EWBG	HINO PROFIA	2011	1	
LDG-FR1EXBG		2010~2011	2	
LKG-FQ1EWBG		2011	2	
LKG-FQ1EWBJ		2011	3	
LKG-FR1AXBG		2011	3	
LKG-FR1EXBG		2010~2012	50	
LKG-FR1EXBJ		2011~2012	19	
LKG-FR1EZBG		2011~2012	3	
LKG-FS1EWBG		2011	2	
LKG-FS1EZBG		2011	2	
LKG-FW1EXBG		2011	22	
LKG-FW1EXBJ		2011	4	
LKG-FW1EYBG		2011	9	
LKG-FW1EYCG		2012	2	
LKG-FW1EZBG		2011	3	
LKG-FW1EZBJ		2011	5	
LKG-FS54VVZ		FUSO	2011	4
LKG-FS55VVZ			2011~2012	7
LKG-FU54VTZ			2011	1
LKG-FU54VUZ	2011~2012		4	
LKG-FV54VUZ	2011~2012		8	
LKG-FY54VTY	2011		1	
LKG-CYJ77A	GIGA	2011~2012	8	
LKG-CYJ77AL		2011~2012	6	
LKG-CYL77A		2011~2012	16	
LKG-CYL77AA		2011	1	
LKG-CYL77AM		2011	1	
LKG-CD5ZA	-	2011~2012	7	
LKG-CG5ZA		2011	1	
LKG-CX5YA		2011	2	
TOTAL			199	