

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2945	DATE	May 30, 2012
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	The engine coolant leaks and drops on the airbag computer due to insufficient maintenance of engine coolant. That could cause the corrosion of heater radiator inside. Continuous use of such vehicle with this condition may cause the engine coolant entering into the airbag computer and then the warning lamp comes on due to short-circuit of the airbag system. In the worst case, the airbag could deploy accidentally in traveling.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E-G301G	PYZAR	1996-2000	7,736
E-G311G			3,680
E-G303G			24,039
E-G313G			5,873
GF-G301G			1,231
GF-G311G			638
GF-G303G			901
			TOTAL