

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	2943	DATE	June 1, 2012
MANUFACTURER	SUMITOMO NACCO MATERIALS HANDLING CO., LTD.		
DESCRIPTION OF DEFECT	The exhaust angle of the vertical-type exhaust silencer as set-up an option was not suitable for a correct direction of 30 degrees or less. If the truck is being used in such condition, the exhaust gas may have a bad influence on other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SA-D2H	FD20P7	2004~2005	6
SB-D3G	FD30P7	2004	2
SG2F	FG25P7	2004	3
SA-D2K	FD25PX	2006	1
SB-D3H	FD30PX	2006~2008	4
SA-SD1E	FD14PX FD15PX	2006~2008	3
EDM-SD1E	FD20PXI	2011	1
SA-SD2E	FD20PX FD25PX	2006~2008	7
EDM-SD2E	FD20PXI	2009~2011	7
SG1H	FG15PX FT15PX FT20PX	2006~2008	6
EBT-SG2H	FG20PXI	2009	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDN-D2L	FD25PXI	2012	2
D5B	FD75P3	1996	1
KDN-D3H	FD30PXI	2008	1
D2H	FD20P7	1997~2002	7
TOTAL			52