

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2954	DATE	June 11.2012
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	At flexible mounting parts in the rear of the cabin, flexible mounting parts could come out due to inappropriate configuration of hold-down metal washer for rubber cushion. Accordingly, the cabin may lean forward in case of sudden stop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-C114	AG6114	2011~2012	42
	AG7114	2011~2012	15
TOTAL			57