

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2953	DATE	20, June, 2012
MANUFACTURER	Kobelco Construction Machinery Co., Ltd.		
DESCRIPTION OF DEFECT	The flushing cycle at the time of malfunction is not adjusted regularly on some of the flusher relay units for the direction indicator lamps. Thereby, if the direction indicator lamps equipped at front or rear side is failed, the display device indicating the operating condition in the driver's compartment will not function properly as far as using it as it is.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-YE04	SK125W	2006 ~ 2012	126
TOTAL			126